

Technical  
Data Sheet



Willamette Valley Company

www.wilvaco.com

800.333.9826

Partnering through service,  
innovation, and integrity

# POLYQuik<sup>®</sup> Bedliner Rejuvenator (AP-160)

## Restores Bedliner to a High Gloss Finish

### DESCRIPTION

Bedliner Rejuvenator is a water-based coating formulated specifically for topcoating spray-on bedliners. This product will return an aged or weathered bedliner to its original glossy Black appearance, and provide the same durable performance expected from the originally installed bedliner (NOTE: This product is not to be applied over glossy bedliners—see Application Section for details). Bedliner Rejuvenator is ready to apply with an industrial grade micro-fiber towel or an applicator sponge.

### WHERE TO USE

- **Truck beds**—weathered or worn spray-on bedliners
- **Utility vehicles**— worn or weathered spray-on bedliners

### FEATURES AND BENEFITS

- **Easy to Use**—apply by sponge
- **Fast Drying**—recoat in 30 minutes
- **Durable Surface**—scratch resistant
- **Glossy Appearance**—restores original appearance

### PACKAGING

8 oz. (236 ml)  
16 oz. (473 ml)

### COLOR

Black

### YIELD

16 oz. (473 ml) covers 33 ft<sup>2</sup> (3.0 m<sup>2</sup>).

### SHELF LIFE

12 months when properly stored.

### STORAGE

Store and ship this product in a clean, dry, low-humidity, shaded or covered environment at 60 to 90°F (15 to 32° C).

## TECHNICAL INFORMATION

### Typical Properties

VOC, lbs/gal (g/L), ASTM D 2369	0.7
Viscosity, cps, ASTM D4878	100
Color	Black

### Cure Time

Temperature, 50% RH	Ready for topcoat, minutes	Maximum recoat time, hrs
60° F (15° C)	30	2
80° F (27° C)	15	1

### Processing Parameters

Application temp, ° F (° C)	60 to 80 (15 to 27)
Recommended thick., mils (mm)	1 to 3 (0.025 to 0.075)
Application equipment	Sponge or industrial grade towel

---

## APPLICATION

---

### SURFACE PREPARATION

1. Remove debris and clean the surface with soap and water or mild degreaser to remove grease and oil contaminants.
2. Allow prepared surface to completely dry before applying product.
3. Place prepared surface in a shaded area away from direct sunlight.
4. Mask off surrounding areas and any area that is not going to be coated.
5. Improve adhesion by lightly abrading with 80 grit sand paper before application of product.
6. Remove sanding dust with compressed air.
7. Evaluate adhesion of prepared surface in a small out of view area.
8. **DO NOT APPLY OVER GLOSSY BEDLINER SURFACES. BEDLINER REJUVENATOR WILL NOT ADHERE TO GLOSSY SURFACES AND OVER TIME WILL PEEL OFF.**
9. Surface must be between 60-80°F, otherwise product will dry too slow or too quickly. For best results, do not apply product beyond these temperatures.

### PROCESSING

1. Secure cap to container and gently mix the product by shaking container.

### APPLICATION

1. Apply product with sponge or industrial grade towel.
2. Only apply 1 to 3 wet mils of product per coat. Do not apply more than 3 wet mils since it will take longer to cure, run, exhibit poor adhesion, crack, fill textured surfaces, and have low gloss.
3. Apply with light pressure using a sponge or industrial grade towel. Heavy pressure will leave debris in the product.
4. Apply in a left-to-right, up-to-down direction to ensure even coverage.
5. One coat should provide adequate coverage. A second coat can be applied after the first coat is dry (within the recoat time).
6. Remove masking while product is still wet and allow coating to cure for 24 hours before returning area to normal use.

### CLEANING & MAINTENANCE

- Immediately clean tools, equipment, and other surfaces with hot soapy water or appropriate solvent.

---

## HEALTH AND SAFETY

---

Willamette Valley Company recommends reading and becoming familiar with the Material Safety Data Sheet before using this product.

### WILLAMETTE VALLEY COMPANY

[www.wilvaco.com](http://www.wilvaco.com)  
[info@wilvaco.com](mailto:info@wilvaco.com)

### DIVISIONS

#### WESTERN DIVISION

1075 Arrowsmith Street  
PO Box 2280  
Eugene, OR 97402  
Tel 541.484.9621  
[www.POLYQUIK.com](http://www.POLYQUIK.com)  
[www.SPIKEFAST.com](http://www.SPIKEFAST.com)

#### EASTERN DIVISION

6662 Marbut Road  
Lithonia, GA 30058  
Tel 888.878.9826

#### MIDWEST DIVISION

1549 Hwy 2  
Two Harbors, MN 55616  
Tel 218.834.3922

#### PRECISION TECHNOLOGIES DIVISION

675 McKinley Street  
Eugene, OR 97402  
Tel 541.484.2368  
[www.pre-tec.com](http://www.pre-tec.com)

#### SOUTHERN DIVISION

100 Dixie Mae Drive  
PO Box 4450  
Pineville, Louisiana 71361  
Tel 318.640.5077

### SUBSIDIARIES

#### CANADIAN WILLAMETTE

325 Edworthy Way  
New Westminster BC V3L 5G4  
Tel. 800.663.4298

#### ECLECTIC PRODUCTS INC.

Corporate Office  
1075 Arrowsmith Street  
Eugene, OR 97402  
Tel 541.284.4667  
[www.eclecticproducts.com](http://www.eclecticproducts.com)

#### IDAHO MILL & GRAIN

445 North 430 West Hwy  
Po Box 188  
Malad City, Idaho 83252  
Tel 208.766.2206

#### TAPEL WILLAMETTE LTD. S.A.

Av. Estero La Posada 3625 Parque  
Industrial Coronel Coronel, Chile  
Tel 011.56.41.928.100  
[www.tapel.cl](http://www.tapel.cl)



---

### DISCLAIMER OF WARRANTY

TEST RESULTS ARE TO BE CONSIDERED AS REPRESENTATIVE OF CURRENT PRODUCTION AND SHOULD NOT BE TREATED AS SPECIFICATIONS. WHILE ALL THE INFORMATION PRESENTED IN THIS DOCUMENT IS BELIEVED TO BE RELIABLE AND TO REPRESENT THE BEST AVAILABLE DATA ON THESE PRODUCTS, NO GUARANTEE, WARRANTY, OR REPRESENTATION IS MADE, INTENDED, OR IMPLIED AS TO THE CORRECTNESS OR SUFFICIENCY OF ANY INFORMATION, OR AS TO THE SUITABILITY OF ANY CHEMICAL COMPOUNDS FOR ANY PARTICULAR USE, OR THAT ANY CHEMICAL COMPOUNDS OR USE THEREOF ARE NOT SUBJECT TO A CLAIM BY A THIRD PARTY FOR INFRINGEMENT OF ANY PATENT OR OTHER INTELLECTUAL PROPERTY RIGHT. EACH USER SHOULD CONDUCT A SUFFICIENT INVESTIGATION TO ESTABLISH THE SUITABILITY OF ANY PRODUCT FOR ITS INTENDED USE.

Revision Date: November 2009